CIVIL QUALITY CONSULTANTS & ENGINEERS

(Buildings Geo-Tech & Highway Materials Testing Laboratory)
An ISO 9001: 2015 Certified Company
NABL Accredited As Per ISO/IEC : 17025:2005 Laboratory

JAS-ANZ
ISO 9001:2000 CERTIFIED

Name of Work : Maintenance of Park in Jalahalli Ward No.16, BBMP, Bangalore.

Name of Client	:	**Executive Engineer,** Rajarajeshwari Nagara Division, BBMP, Bangalore..
Contractor/Agency	:	**Sri. S Santhosh Kumar,** Contractor, Bangalore
Total Cost	:	Rs. 4.98 Lakhs
Date of Inspection	:	02.08.2019
Status of Bill	:	1st & Final Bill
In the Presence of	:	(a) **Assistant Engineer (W. No.16),** BBMP, Bangalore.
	:	(b) **Mr. Naveen Kumar,** Engineer M/s Civil Quality Consultants & Engineers, Bangalore.

PMC Report

Sl.No	Description of the Item		Comments / observations
1	Site / jungle clearence : Cutting and Clearing the jungle Including removal roots with initial lead.....	:	Work done up to the billed quantity and Quality is satisfactory
2	Shrubs in groups Developing the area for shrubs by digging to a depth of 0.45m.....	:	Work done up to the billed quantity and Quality is satisfactory
3	Shrubs in Groups cost of the plant (8plant per Sqm).....	:	Work done up to the billed quantity and Quality is satisfactory
4	Planting of Specimen plants Digging pits size 0.75m x 0.75mx 0.75 filling upto 50% the pits.....	:	Work done up to the billed quantity and Quality is satisfactory
5	Digging pits size 0.75 x0.75m 0.75 filling upto 50% the pits with top excvated soil and reaining 50% with sand.....	:	Work done up to the billed quantity and Quality is satisfactory

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಯಶವಂತಪುರ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Office & Laboratory : # 133, Bhuvaneshwarinagar, Dodda Basti Main Road, Bangalore - 560 056.
e-mail:civilqualityconsultants@gmail.com Ph: 080-23240644 / Mob: 8553518550

Scanned by CamScanner

6	Digging pits size 0.75 x0.75m 0.75 filling upto 50% the pits with top excvated soil and reaining 50% with sand.....	:	Work done up to the billed quantity and Quality is satisfactory
7	Supplying of red soil (New Earth filling) Supply of good quality Road soil for gardening.....	:	Work done up to the billed quantity and Quality is satisfactory
8	Sprinkler System : Providing and fixing of Srinkler system with the site.....	:	Work done up to the billed quantity and Quality is satisfactory

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

For CIVIL QUALITY CONSULTANTS & ENGINEERS

Authorised Signatory

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಯಶವಂತಪುರ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

Scanned by CamScanner